

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/04/2021

Submitted Date:

06/04/2021

Document Number:

690007646

**FIELD INSPECTION FORM**
 Loc ID 332634 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289956	WELL	TA	03/01/2019	OW	123-24974	KARAKAKES H13-33	TA
290257	WELL	TA	05/22/2020	OW	123-25032	KARAKAKES H 13-25	TA
425613	WELL	TA	03/11/2020	OW	123-34446	Karakakes H14-63HN	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	60 Bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	53				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.221680,-104.619830
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above****AirsID**

API Number	API Number	AirsID
123-25032		
123-24974		
123-34446		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 289956 Type: WELL API Number: 123-24974 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Not connected to flow line.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 290257 Type: WELL API Number: 123-25032 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in at wellhead.  
No Flow Line Observed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 425613 Type: WELL API Number: 123-34446 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No Flow Line Observed at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Location signage indicating battery shut in.</u>	carlilec	06/04/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690007647	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447761">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447761</a>