

Inspection Photos  
Operator: Logos  
API: 067-09207  
Date: 6/3/2021



Photo 1. View of project area from the well pad entrance facing center.





Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, smooth brome, rubber rabbitbrush, and crested wheatgrass. Revegetation at final reclamation will need to use a native seed mix representative of the reference area.





Photos 3. View of the western project area from the northwestern corner facing southward.





Photos 4. View of reference area comprised of big sagebrush and black sagebrush shrubland with scattered pinyon and juniper trees, and squirreltail, western wheatgrass, mat penstemon in the understory.