

Inspection Photos
Location Name: Nielson #5
API: 05-007-06141



Soil berm has been pushed up over impacted material.



Nielson #5 well head and surrounding soil are wet and stained with oil.