

**Inspection Photos**  
**Location Name: Fitzhugh #6**  
**API: 05-007-05038**



**Fitzhugh #6 well head and pump jack.**



**Well head and surrounding area is wet and stained with oil.**



**Inspection Photos**  
**Location Name: Fitzhugh #6**  
**API: 05-007-05038**



**Fitzhugh #7 PA marker and abandoned flow line.**



**Land farm treatment cells.**

**Inspection Photos**  
**Location Name: Fitzhugh #6**  
**API: 05-007-05038**



**View of land farm treatment cells.**



**Drip pan is overflowing.**