

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/01/2021

Submitted Date:

06/01/2021

Document Number:

699103760

FIELD INSPECTION FORM
 Loc ID 332100 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270169	WELL	TA	07/01/2019	GW	123-21834	ARD C 6-3JI	TA

General Comment:

This is a follow up to FIRR document #402699048. CA's did not meet expectations.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	The capacity label for the pit is faded. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	06/04/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	06/04/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Gas meter run wil need to be calibrated before returning to production.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 270169 Type: WELL API Number: 123-21834 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 6/1/21 at approximately 0741hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402699048 at ARD C 06-29D of Noble Energy, at Location ID # 332100 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 6/4/21.</p> <p>The capacity label for the pit is faded. Install sign to comply with Rule 605.g. With a corrective action date of 6/4/21.</p> <p>Gas Meter will need to be calibrated when location is put back into production. See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	06/01/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402705111	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444446
699103761	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444440