

# Inspection Photos

API: 073-06324

Operator: NIGHTHAWK PRODUCTION LLC

Inspection Date: 6/2/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 1.** Facing north along the access road which was mostly pre-existing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 2.** Facing northeast toward the access road which was not pre-existing. Arrow points to the location approximately 330 ft. away.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 3.** Facing northeast toward the location. The perimeter fence remains around the location in good condition.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 4.** Facing north at the center of the location. The vegetation has uniformly re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 5.** Facing west at the center of the location. The vegetation has uniformly re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 6.** Facing south at the center of the location. The vegetation has uniformly re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 7.** Facing east at the center of the location. The vegetation has uniformly re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021

## Inspection Photos



**Photo 8.** Facing east toward the undisturbed surrounding rangeland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06324 | Date: 6/2/2021