

Inspection Photos

API: 073-06312

Operator: NIGHTHAWK PRODUCTION LLC

Inspection Date: 6/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 1. Facing northeast toward the location. The perimeter fence remains around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 2. Facing northeast at the location. There is desirable vegetation establishment throughout most areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 3. Facing northwest at the location. This area consists mostly of undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 4. Facing southeast at the location. This area consists mostly of undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 5. There is List B noxious weeds Russian knapweed present at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 6. West side of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021

Inspection Photos



Photo 6. Facing west. Powerline utility remains to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06312 | Date: 6/2/2021