

Inspection Photos
Location Name: Federal Sandwash 2-1
Location ID: 313040



Photo 1. Overview of location taken facing northeast.



Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: Federal Sandwash 2-1
Location ID: 313040



Photo 3. Produced water tank with corrosion. Tank does not appear to be in use. Tank must be removed if not in use.



Photo 4. Close up of corrosion in tank from photo 3.

