

Inspection Photos

6/08/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312512

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312512



Photo 1: Photo taken from the south end of the Location facing northwest. Photos 1-3 provide an overview of the Location from northwest, north, to northeast. Photos show reclamation activities including, but not limited to, removal of gravel, compaction alleviation, recontouring/regrading and revegetation of both the Location and access road have not been performed.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312512



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312512



Photo 3: See comments under photo 1. .

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312512

Timestamp Camera



20210608

Photo 4: Photo taken from the east end of the Location, facing west. See comments under photo 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312512



Photo 5: Photo taken from the northwest end of the Location, facing southeast. Photo shows sign at former tank battery.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312512



Photo 6: Photo taken from the access road, facing north. Photo shows access road has not been reclaimed.

