

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 1 – Signs at Entrance

Photo 2 – Tank Battery

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 3 – ECD and Flare




Photo 4 – Unmarked Risers at Compressor



Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 5 – Compressor



Photo 6 – Heater Treaters

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 7 – Unmarked Risers South of Heater Treaters