

Inspection Photos

6/08/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 334518

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334518



Photo 1: Photo taken from the cut slopes on the south end of the Location, facing east. Southern areas of the Location are not progressing towards 1003 standards. Areas require additional revegetation activities and control measures to stabilize soils until longer term stabilization is achieved.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 334518



Photo 2: Photo taken from the cut slopes on the south end of the Location, facing south. Southern areas of the Location are not progressing towards 1003 standards. Areas require additional revegetation activities and control measures to stabilize soils until longer term stabilization is achieved.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334518



Photo 3: Photo taken from the southern interim areas of the Location, facing west. Photo shows areas where uniform desirable vegetation establishment has not been achieved.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334518



Photo 4: Photo taken from the northern interim areas of the Location. Areas on the north and east end of the Location appear to meet 1003 uniform vegetative standards.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 334518



Photo 5: Photo taken from the location entrance, facing west. Photo shows noxious weeds (Bindweed, white flowers).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334518



Photo 6: Photo taken from the west end of the Location, facing southwest. Photo shows noxious weeds (Hoary cress/Whitetop).