

Inspection Photos
Operator: Paradox Upstream
API: 113-06099
Date: 6/8/2021



Photo 1. View the project area from the northern edge facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with James galleta, western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photos 4. View of reference area comprised of sagebrush shrubland with an understory of James galleta, needleandthread grass, and sego lily.