

Inspection Photos
Operator: Paradox Upstream
API: 113-06109
Date: 6/8/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with James galleta, western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of erosional channel forming where concentrated stormwater runs off of the northwestern edge of the well pad. Channel is approximately 6-8 inches wide and deep.



Photos 4. View of reference area comprised of sagebrush shrubland with an understory of James galleta, needleandthread grass, and sego lily.