

Inspection Photos

6/10/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324218

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324218



Photo 1: Photo taken from the interim areas on the south end of the Location. Photo shows soil surface on the interim areas. Inspector observed evidence that Operator conducted hydro-seeding activities on the interim areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324218



Photo 2: Continued from photo 1. Photo shows soil surface on the interim areas. Inspector observed evidence that Operator conducted hydro-seeding activities on the interim areas.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324218



Photo 3: Photo taken from the south end of the Location, facing south. Photo shows Operator has implemented a sediment trap; inlet/outlet of trap observed to be constructed with a geotextile lining and rock armoring.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324218



Photo 4: Photo taken from the east end of the Location, facing north. Photo shows Operator has implemented a sediment trap; inlet/outlet of trap observed to be constructed with a geotextile lining and rock armoring.

