

Inspection Photos
Operator: Paradox Upstream
API: 113-06074
Date: 6/9/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of erosional channel forming within the northern project area. Channel is approximately 18-24 inches wide and 8-10 inches deep.



Photo 3. View of the western project area facing southwestward. Little desirable vegetation observed here. Green vegetation is largely weedy kochia.



Photo 3. View of scattered debris observed within the project area.



Photo 6. View of reference area comprised of pinyon and juniper woodland with an understory of mountain mahogany, *Tetrandris* sp., ephedra, yucca, and Indian ricegrass.