

Stormwater Inspection Report

Operator:	Laramie Energy, LLC
Project:	Cascade Creek
Location:	Cascade Creek 697-03-07 Access Road
Date:	Tuesday, June 15, 2021
Weather:	Hazy, Light Wind, 103°, Lo 57°



Type of Inspection Report	14-Day Routine	Monthly Routine	Post-Storm	Corrective Action	Winter Exclusion	Stabilization Complete	Site Review
				X			

Phase(s) of Construction Inspected	No Activity	Clear & Grade	Facility Installation	Drilling Operations	Reclamation	Acres of Disturbance Inspected
	X					0

Stormwater Compliance Questions		YES	NO	N/A
1	Any BMPs Fail or Require Maintenance?		X	
2	Any Issues Identified Requiring the Installation of Additional BMPs?	X		
3	Any Sediment or Other Pollutants Discharged Outside Project Boundaries?		X	
4	Any BMPs Repaired or Maintained?		X	
5	Any New BMPs Installed?	X		
6	Any Hazardous Materials Spilled or Leaked?		X	
7	Any Deviation from the Minimum Inspection Schedule?		X	

Comments / Descriptions / Explanations	
<p>D&D Hydroseeding was contracted to make a hydromulch application along the Cascade Creek 697-03-07 access road. The application was made to address COGCC's request to provide additional erosion protection on the access road cut slope near the CC 697-03-07 pad. 1,600 gallons of tackified mulch was applied.</p>	

Photo 1



Applying Hydrmulch on the CC 697-03-07 Access Road

Photo 2



Applying Hydrmulch on the CC 697-03-07 Access Road

Photo 3



Hydromulch Application on the CC 697-03-07 Access Road

Photo 4



Hydromulch Application on the CC 697-03-07 Access Road

Inspector Name and Title

Mark Carlson, Environmental Inspector

Mark Carlson

Inspector Signature

6/15/2021

Date of Signature

Part I.A.3.f. Compliance Signature Requirement

"I verify that, to the best of my knowledge and belief, all corrective action and maintenance items identified during the inspection are complete, and the site is currently in compliance with the permit."

Stormwater Manager Certification Signature