

Inspection Photos

6/15/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 324457

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 1: Photo taken from the west end of the Location, facing east. Photo shows Location has not been reclaimed in accordance with 1004 Rules.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 2: Photo shows anchor equipment remaining on the northwest end of the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 3: Photo taken from the east end of the Location, facing west. Photo shows Location has not been reclaimed in accordance with 1004 Rules.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 4: Photo taken from the southeastern areas of the Location. Photo shows areas where production equipment was located. Photo shows gravel remains on the Location, and areas have not been reclaimed in accordance with 1004 Rules.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 5: Photo shows noxious weeds (Musk thistle) establishing on the southeastern areas of the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 6: Photo taken from the access road, facing northeast. Photo shows access road has not been reclaimed in accordance with 1004 Rules.