

# Inspection Photos

API: 055-06212

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/16/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021

## Inspection Photos



**Photo 1.** Facing west toward the access road which was not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021



## Inspection Photos



**Photo 2.** Facing west toward the location. The location was never recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021



## Inspection Photos



**Photo 3.** Facing west along the fill slope of the location. The location consists predominately of noxious weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021

## Inspection Photos



**Photo 4.** Facing east at the location. The location consists predominately of noxious weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021



## Inspection Photos



**Photo 5.** View of noxious weeds observed at the location include: Cheat grass, Red stem filaree, Field bind weed, and Jointed Goat grass.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021



## Inspection Photos



**Photo 6.** View of Jointed goatgrass found on the location which is a List B noxious weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021



## Inspection Photos



**Photo 7.** Facing northwest toward the cut slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/16/2021