

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2021

Submitted Date:

06/18/2021

Document Number:

700702882

## FIELD INSPECTION FORM

 Loc ID 335898 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name     | Phone        | Email                          | Comment                     |
|------------------|--------------|--------------------------------|-----------------------------|
| clark, Erin      | 405-319-3250 | erin.k.clark@exxonmobil.com    | Lead regulatory coordinator |
| Thomson, Bud     |              | BLThomps@BLM.gov               |                             |
| Sutton, Derek    |              | derek_sutton@xtoenergy.com     |                             |
| Dooling, Jessica | 832-624-0810 | jessica.dooling@exxonmobil.com |                             |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 294138      | WELL | PR     | 01/01/2021  | GW         | 103-11157 | PICEANCE CREEK UNIT 297-12A1 | PR          |
| 294142      | WELL | PR     | 02/13/2010  | GW         | 103-11158 | PICEANCE CREEK UNIT 297-12A2 | PR          |
| 294201      | WELL | PR     | 04/01/2020  | GW         | 103-11160 | PICEANCE CREEK UNIT 297-12A3 | PR          |
| 294202      | WELL | PR     | 02/13/2010  | GW         | 103-11161 | PICEANCE CREEK UNIT 297-12A7 | PR          |
| 294203      | WELL | PR     | 01/01/2019  | GW         | 103-11162 | PICEANCE CREEK UNIT 297-12A9 | PR          |
| 294204      | WELL | PR     | 01/01/2021  | GW         | 103-11163 | PICEANCE CREEK UNIT 297-12A5 | PR          |
| 294205      | WELL | PR     | 07/01/2017  | GW         | 103-11164 | PICEANCE CREEK UNIT 297-12A6 | PR          |
| 294206      | WELL | PR     | 07/17/2009  | GW         | 103-11165 | PICEANCE CREEK UNIT 297-12A8 | PR          |
| 294207      | WELL | PR     | 05/31/2012  | GW         | 103-11166 | PICEANCE CREEK UNIT 297-12A4 | PR          |

**General Comment:**

COGCC Inspection Report Summary

On Thursday 6/17/2021 at approximately 0900, I, Inspector Scott Ramsey, conducted a routine inspection at XTO T14X-13G, at Location # 316259 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

During this inspection the following possible compliance issues were observed:

1. Debris around wells
2. Regulator was leaking gas (I contacted Zack Simpson the lead for XTO and he informed me that someone would be out to fix it immediately)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  | L      |  | Date: |

Overall Good:

|                      |            |  |       |
|----------------------|------------|--|-------|
| <b>Signs/Marker:</b> |            |  |       |
| Type                 | WELLHEAD   |  |       |
| Comment:             |            |  |       |
| Corrective Action:   |            |  | Date: |
| Type                 | CONTAINERS |  |       |
| Comment:             |            |  |       |
| Corrective Action:   |            |  | Date: |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

|                           |  |  |                         |
|---------------------------|--|--|-------------------------|
| <b>Good Housekeeping:</b> |  |  |                         |
| Type                      | OTHER  |  |                         |
| Comment:                  | Regulator at manifold was leaking gas (I contacted Zack Simpson the lead for XTO and he informed me that someone would be out to fix it immediately) |  |                         |
| Corrective Action:        |  |  | Date:                   |
| Type                      | DEBRIS   |  |                         |
| Comment:                  | Random debris aroung well heads  |  |                         |
| Corrective Action:        | remove debris  |  | Date: <u>06/25/2021</u> |

Overall Good:

|  |                      |        |  |
|--|----------------------|--------|--|
| <b>Spills:</b>   |                      |        |  |
| Type   | Area                 | Volume |  |
| In Containment: No                                     |                      |        |  |
| Comment:   | <input type="text"/> |        |  |
| <input type="checkbox"/> Multiple Spills and Releases? |                      |        |  |

|                                   |  |  |                 |
|-----------------------------------|--|--|-----------------|
| <b>Equipment:</b>                 |  |  | corrective date |
| Type: Horizontal Heated Separator | # 1  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Ancillary equipment         | # 4  |  |                 |
| Comment:                          | chemical tanks at manifold in metal containments |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Bradenhead                  | # 9  |  |                 |
| Comment:                          | Braden heads have a manual gauge for monitoring  |  |                 |
| Corrective Action:                |  |  | Date:           |

|                    |     |       |  |
|--------------------|-----|-------|--|
| Type: Plunger Lift | # 9 |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     | Date: |  |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities  |           |       |      |             |           |         |    |               |    |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 294138    | Type: | WELL | API Number: | 103-11157 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294142    | Type: | WELL | API Number: | 103-11158 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294201    | Type: | WELL | API Number: | 103-11160 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294202    | Type: | WELL | API Number: | 103-11161 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294203    | Type: | WELL | API Number: | 103-11162 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294204    | Type: | WELL | API Number: | 103-11163 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294205    | Type: | WELL | API Number: | 103-11164 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 294206    | Type: | WELL | API Number: | 103-11165 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             | Date:     |         |    |               |    |

Facility ID: 294207 Type: WELL API Number: 103-11166 Status: PR Insp. Status: PR

**Producing Well**

Comment: [producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
|                  |                 | Waddles                 |                       |               |                          |         |
|                  |                 | Sediment Traps          |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 700702885    | photo log   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459274">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459274</a> |