

Inspection Photos

API#057-06004

Operator: Kauffman

Insp#: 692403515

Insp Date: 8/10/2021



Photo#1:

View over Location to Northeast.

June 10, 2021



Photo#2:
View over Location to West.

June 10, 2021



Photo#3:
Area where sparse vegetation has emerged.



Photo#4:
Desiccated Russian thistle along Southeast edge of site.

June 10, 2021



Photo#5:
Reference area.

June 10, 2021