

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2021

Submitted Date:

06/19/2021

Document Number:

696104670

FIELD INSPECTION FORM

Loc ID 422686 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422687	WELL	PR	01/01/2020	OW	123-33351	WILSON PC AC20-10	PR

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Calibration card indicates calibration within last year. Last calibration: 12/07/2020. Active w/ production.		
Corrective Action:			Date:

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Concrete vault sump for gas engine exhaust (2 Bbls.)		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor. Controls crude oil tanks vapors. Pilots: ON.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ crude oil tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.559021,-104.451524
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ produced H2O vault.					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 422687 Type: WELL API Number: 123-33351 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/26/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 06/17/2021 at approximately 13:41 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WILSON PC /AC20-10 Location ID: 422686 Well Name(s): Wilson PC AC20-10. API: 05-123-33351. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104671	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459380