

Inspection Photos

Loc#416625

Operator: Sandridge

Insp#: 692403517

Insp Date: 6/10/2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

June 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise-Damfino Loc#416625



Photo#2:
Work recently conducted on cut slope 11/19/20.



Photo#3:
Cut slope 6/10/21.

June 10, 2021



Photo#4:
Work recently conducted on cut slope 11/19/20.

Photo#5:
Cut slope 6/10/21.

June 10, 2021



Photo#6:
Front/West side of Spoils pile.

Photo#7:
Back/East side of Spoils pile.

June 10, 2021



Photo#8:
New BMP installed at Northeast corner of Pad.



Photo#9:
Debris weeds area of concern.

June 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise-Damfino Loc#416625