


**Inspection Photos**  
**Location Name: Gnat Hill 1-29**  
**Location ID: 425278**



**Photo 1. Overview of location taken at entrance facing west.**



**Photo 2. Stained soil at wellhead.**

