

Inspection Photos  
Location Name: Harsch 1  
Location ID: 321319



Photo 1 WH sign



Photo 2 WH

# Inspection Photos

Location Name: Harsch 1  
Location ID: 321319



Photo 3 TB sign



Photo 4 TB

Inspection Photos  
Location Name: Harsch 1  
Location ID: 321319



Photo 5 Gas Meter Run




Photo 6 Card in meter house indicates that calibration is not current





**Inspection Photos**  
**Location Name: Harsch 1**  
**Location ID: 321319**



**Photo 7 ECD and Horizontal Heated Separator**