

Crestone Peak Resources Operating LLC, Cottonwood Creek 4-65 28-27 3AH

005-07464

Inspection #688310649

6/11/2021

Surface Cementing Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.67567, -104.67867, 5652.9ft, 204°
06/11/2021 01:00:33 PM



Colorado Oil and Gas Conservation Commission

39.67552, -104.67574, 5600.4ft, 255°

06/11/2021 01:04:31 PM



Colorado Oil and Gas Conservation Commission
39.676, -104.67582, 5633.2ft, 222°
06/11/2021 01:08:02 PM



Cement to
surface at 1546
pm.

Colorado Oil and Gas Conservation Commission
39.67541, -104.67655, 5616.8ft, 338°
06/11/2021 03:41:27 PM




Conex for
covering drilling
materials.

Colorado Oil and Gas Conservation Commission
39.67515, -104.67703, 5593.8ft, 137°
06/11/2021 01:18:23 PM



Location
construction
showing layers
of soil removed.

Colorado Oil and Gas Conservation Commission
39.67513, -104.67741, 5561.0ft, 213°
06/11/2021 01:17:50 PM



Colorado Oil and Gas Conservation Commission
39.67536, -104.67612, 5629.9ft, 154°
06/14/2021 07:59:39 PM



Location
construction
showing heavy
equipment
tracking
parallel on a
steep slope.


Colorado Oil and Gas Conservation Commission
39.67527, -104.67568, 5590.6ft, 294°
06/11/2021 02:04:49 PM



Colorado Oil and Gas Conservation Commission
39.6668, -104.66655, 5625.0ft, 187°
06/11/2021 03:42:24 PM



Colorado Oil and Gas Conservation Commission
39.67625, -104.6761, 5600.4ft, 300°
06/15/2021 05:38:13 PM



Colorado Oil and Gas Conservation Commission
39.67625, -104.67611, 5600.4ft, 12°
06/15/2021 05:38:16 PM