

Although the Burkett 1-3 well is near the scotch thistle noted in photo 3 of the inspection report, the scotch thistle is outside of the well pad disturbance and within the Simcoe pipeline right-of-way ("ROW"). Please see attached map of general location of Simcoe pipeline and attached picture of Simcoe pipeline markers.



