

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/23/2021

Submitted Date:

06/23/2021

Document Number:

699103914

FIELD INSPECTION FORM

Loc ID 414881 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414994	WELL	SI	07/01/2020	GW	123-30941	STINAR C 13-32	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 414994 Type: WELL API Number: 123-30941 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/23/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 6/23/21 at approximately 0855 I, Inspector Adam Burns,
 Conducted an on-site inspection at Stinar C 13-32 of Noble Energy
 Location ID: 414881 in Weld County, Colorado.
 While there, I observed a well that is PR.
 No violation of the COGCC rules were observed at the time of inspection.
 This is a summary of inspection report.

burnsa

06/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103915	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462060