

**Inspection Photos**  
**Location Name: Shiras CTB S11**  
**Location ID: 451937**




**Photo 1. Overview of location taken at entrance facing north.**



**Photo 2. Entrance sign inaccurate.**



**Inspection Photos**  
**Location Name: Shiras CTB S11**  
**Location ID: 451937**



**Photo 3. Battery sign inaccurate.**



**Photo 4. Tank labels inaccurate.**

