

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2021

Submitted Date:

06/23/2021

Document Number:

689805916

FIELD INSPECTION FORMLoc ID 448834 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

8 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Boyer, David	303-994-0000	david@d90energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448969	WELL	PR	09/30/2017	OW	057-06593	Grizzly 0881 2-1H36	SI
448970	WELL	PR	09/01/2020	OW	057-06594	Grizzly 0881 4-1H36	SI
448974	WELL	PR	07/03/2018	OW	057-06597	Peters 0781 16-12H13	SI

General Comment:

Routine follow up inspection. Follow up to inspection from 4/8/2021 document number 689805644. No corrective actions appear to have been met. Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676796, form remains In Process.

Signs incomplete/inaccurate
Gas meter not calibrated annually

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section. Signs must be updated 60 days after approval of Form 9.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/21/2021
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. Tank labels should contain: name of operator, operator emergency contact number, tank capacity, tank contents, NFPA label. Signs must be updated 60 days after approval of Form 9.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/21/2021
Type	BATTERY		
Comment:	Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section. Signs must be updated 60 days after approval of Form 9.		
Corrective Action:	Install sign to comply with Rule 605.a. Install sign to comply with Rule 605.e.	Date:	05/21/2021

Emergency Contact Number:

Comment: 713-227-0391

Corrective Action: Install sign to comply with Rule 605.g.

Date: 05/21/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter not calibrated annually.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	05/21/2021
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 3		
Comment:			

Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected FacilitiesFacility ID: 448969 Type: WELL API Number: 057-06593 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 07/22/2021Facility ID: 448970 Type: WELL API Number: 057-06594 Status: PR Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 07/22/2021Facility ID: 448974 Type: WELL API Number: 057-06597 Status: PR Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 07/22/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
Gravel						
Compaction						
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689805917	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462747