

Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 1. Overview of location taken facing east.



Photo 2. Hole in produced water tank.



Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 3. Evidence of apparent spill remains.



Photo 4. Evidence of apparent spill remains.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 5. Evidence of apparent spill remains.




Photo 6. Meter calibrated 6/9/2020.