

Inspection Photos
Location Name: Spetter 5-8
Location ID: 312987



Photo 1. Overview of location taken facing northwest.




Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: Spetter 5-8
Location ID: 312987



Photo 3. No tank label. No berm.



Photo 4. No meter calibration displayed.

