

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON D20 696 /

Location ID: 335161



Photo #4167 from entrance to location.



Photo #4168 No battery sign located at the tank battery.

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON D20 696 /

Location ID: 335161



Photo #4169 Location lacks stabilization.



Photo #4170 No form of tracking control located at the entrance to location

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON D20 696 /

Location ID: 335161



Photo #4171 North Parachute creek from location.