

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335088



Photo #4175 from entrance to location.



Photo #4176 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335088



**Photo #4177 No battery sign located at the tank battery.**