

## Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S96W /7SWSE

Location ID: 334691



Photo #4240 from entrance to location.



Photo #4241 No battery sign located at tank battery.