

# Inspection Photos

6/30/2021

Operator: CHEVRON USA INC - 16700

Location ID: 397191

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



June 30, 2021  
40.11600661N 108.86970131W

**Photo 1:** Photo taken from the reclamation areas on the north end of the Location, facing south. Photo shows sign and areas where additional reclamation activities have been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 2:** Photo taken from the reclamation areas on the north end of the Location, facing east. Photo shows additional reclamation has been performed.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 3:** Photo taken from the reclamation areas on the north end of the Location, facing southwest. Photo shows additional reclamation has been performed.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 4:** Photo shows starting point for the germination transect, facing south.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 5:** Photo shows soil surface for the 50<sup>th</sup> point of the germination transect; desirable plant germination not evident, or negligible.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



June 30, 2021  
40.11589032N 108.86950747W

**Photo 6:** Photo of the transects 50<sup>th</sup> point, facing northwest.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 7:** Photo of the transects 50<sup>th</sup> point, facing southeast.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 8:** Photo taken from the well Location, facing southwest. Photo shows PA marker and shut off valve. Photo also shows weed establishment.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 397191



**Photo 10:** Continued from photo 9. Photo shows weed establishment, including noxious weeds (Halogeton).

