

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON /O13 697

Location ID: 324393



Photo #4288 from entrance to location.



Photo #4289 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON /O13 697

Location ID: 324393



Photo #4290 No battery sign located at the tank battery.



Photo #4291 Unused hoses in tank containment.