

Inspection Photos  
Location 111692  
REM Project # 15761  
Inspection Date: 6/17/2021  
All Photos taken by Kris Neidel



Photo #1 Sign at entry to location

Inspection Photos  
location 111692  
REM Project # 15761  
Inspection Date: 6/17/2021  
All Photos taken by Kris Neidel



Photo #2 looking into pit, to the west-northwest.

Inspection Photos  
location 111692  
REM Project # 15761  
Inspection Date: 6/17/2021  
All Photos taken by Kris Neidel



Photo #3 looking north to pit from pad elevation.

Inspection Photos  
location 111692  
REM Project # 15761  
Inspection Date: 6/17/2021  
All Photos taken by Kris Neidel



Photo #4 west side of pit bottom.

Inspection Photos  
location 111692  
REM Project # 15761  
Inspection Date: 6/17/2021  
All Photos taken by Kris Neidel



Photo #5 Stockpiled soil

Inspection Photos  
Location 111692  
REM Project # 15761  
Inspection Date: 6/17/2021  
All Photos taken by Kris Neidel



Photo #6 equipment on location.