

Inspection Photos
Location Name: McCallum Unit 95
Location ID: 324648



Photo 1. Overview of location taken at entrance facing south.



Photo 2. No bradenhead access apparent.

