

Inspection Photos
Location Name: Sullivan, M C SWD 1
Location ID: 315800



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Sullivan, M C SWD 1
Location ID: 315800



Photo 2. 50 psi on injection tubing at time of inspection.



Photo 3. Noxious weeds (houndstongue) on location.

