

Inspection Photos
Location Name: Grant Tank Battery
Facility ID: 446608



Photo 1 Eastern excavation, from northeast corner looking south



Photo 2 Eastern excavation, from northeast corner looking west

Inspection Photos
Location Name: Grant Tank Battery
Facility ID: 446608



Photo 3 Eastern excavation, looking at flowlines exposed in western excavation wall



Photo 4 Western excavation, looking southwest



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Grant Tank Battery
Facility ID: 446608



Photo 5 Staged equipment in southwest corner of site



Photo 6 Eastern excavation, from southwest corner looking east



Inspection Photos
Location Name: Grant Tank Battery
Facility ID: 446608



Photo 7 Eastern excavation, from southwest corner looking north

