

Inspection Photos
Location Name: Pete Montoya 1
Location ID: 311280



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Pete Montoya 1
Location ID: 311280



Photo 3 Gas Meter Run



Photo 4 weeds growing around Horizontal Heated Separator

Inspection Photos
Location Name: Pete Montoya 1
Location ID: 311280



Photo 5 TB sign



Photo 6 weeds growing around TB and throughout berm

Inspection Photos
Location Name: Pete Montoya 1
Location ID: 311280



Photo 7 weeds growing around ancillary equipment



Photo 8 weeds growing around TB and throughout berm

Inspection Photos
Location Name: Pete Montoya 1
Location ID: 311280



Photo 9 weeds growing on berm by flow line manifold




Photo 10 weeds growing around flow line manifold

Inspection Photos
Location Name: Pete Montoya 1
Location ID: 311280



Photo 11 weeds growing around WH



Photo 12 Pump Jack