

Inspection Photos
Operator: Simcoe
API: 067-09566
Date: 7/13/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with crested wheatgrass and rubber rabbitbrush.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of dense halogeton plants growing along the access road. Approx. 2000 observed.



Photo 5. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, purple threeawn, and threadleaf sunflower.