

Inspection Photos
Operator: Simcoe
API: 067-07432
Date: 7/13/2021



Photo 1. View the project area from the northwestern corner of the working area facing center. Tall (~2 ft) kochia plants need management.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the southern project area from the southwestern corner facing northward.



Photo 4. View the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, purple threeawn, and threadleaf sunflower.