

**Inspection Photos**  
**Location Name: Routt Bonanza 1-22**  
**Location ID: 316756**



**Photo 1. Overview of location taken facing southeast.**



**Photo 2. Wellhead sign does not comply with new sign rules.**





**Inspection Photos**  
**Location Name: Routt Bonanza 1-22**  
**Location ID: 316756**



**Photo 3. Battery sign does not comply with new sign rules.**



**Photo 4. Battery sign does not comply with new sign rules.**



**Inspection Photos**  
**Location Name: Routt Bonanza 1-22**  
**Location ID: 316756**



**Photo 5. Tank labels do not comply with new sign rules.**



**Photo 6. Tank label does not comply with new sign rules.**





**Inspection Photos**  
**Location Name: Routt Bonanza 1-22**  
**Location ID: 316756**



**Photo 7. Water truck stored on location.**



**Photo 8. Grader stored on location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources