

Inspection Photos

7/12/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324040

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324040



Photo 1: Photo taken from the south end of the Location, facing east. Photos 1-3 provide an overview of the Location from east, south to west. Photos show interim reclamation has been performed, and is in process.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324040



Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324040



Photo 3: See comments under photo 1.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324040



Photo 4: Photo shows a soil binder has been implemented to stabilize the soils of the interim area.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324040



July 12, 2021
39.58715747N 108.28198625W

Photo 5: Photo shows unused t-post equipment stored on the Location.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324040



July 12, 2021
39.58701689N 108.28192776W

Photo 6: Photo shows unused cellar cover equipment stored on the Location.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324040



Photo 7: Photo shows unused t-post equipment stored on the Location.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324040



Photo 8: Photo shows unused t-post equipment stored on the Location.

