

# Inspection Photos

API: 125-08205

Operator: J W OPERATING COMPANY

Inspection Date: 7/13/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 125-08205 | Date: 7/13/2021

## Inspection Photos



**Photo 1.** There is an active well at the location. No sign DEVLIN 3-9 abandoned well.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 125-08205 | Date: 7/13/2021