

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NESW

Location ID: 334342



Photo #4476 from entrance to location.



Photo #4477 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NESW

Location ID: 334342



Photo #4478 Location lacks stabilization.



Photo #4479 Location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /2NESW

Location ID: 334342



Photo #4480 No form of tracking BMP at entrance to location.

