

Inspection Photos

7/12/2021

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 423345
Moffat County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



July 14, 2021
40.5014407N 107.72257078W

Photo 1: Photo taken from the northeast end of the Location, facing south. Photos 1-3 provide an overview of the Location from south, southwest to west. Records indicate equipment observed remaining belongs to surface owner; 502.b SOVR submitted requesting pad be left for storage



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



July 14, 2021
40.50145125N 107.72257094W

Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



July 14, 2021
40.50144605N 107.72257185W

Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 4: Photos 4-5 shows cut slope of the Location remains predominantly bare and exposed soil; uniform vegetation has not established on cut slopes of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 5: See comments under photo 4.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



July 14, 2021
40.50122638N 107.72339159W

Photo 6: Photo taken from the northwest end of the Location. Photo shows noxious weeds (Scotch thistle) observed on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 7: Photo taken from the north end of the Location. Photo shows area where stormwater runoff from the pad has created a gully on the fill slopes. Ensure control measures to manage stormwater runoff from the location is implemented and maintained in proper functioning condition to prevent site degradation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 8: Photo shows gully erosion on the fill slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 9: Photo taken from the cut slope along the access road. Photo shows areas where stormwater runoff to the road concentrates; erosion degradation evident.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 10: Photo taken from the access road, facing northeast. Photo shows control measures to manage stormwater runoff and prevent degradation is missing or insufficient; erosion degradation within ditch evident; velocity checks no longer in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 11: See comments under photo 10.



Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



Photo 12: Photo shows noxious weeds (Scotch thistle) observed along access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 423345



July 14, 2021
40.530574N 107.6631521W

Photo 13: Photo shows noxious weeds (Canada thistle) observed along the access road at the access road entrance.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources