

Inspection Photos
Location Name: EWS 4A
Location ID: 448844



Photo 1 Weeds growing in front of WH sign



Photo 2 weeds growing around WH

Inspection Photos
Location Name: EWS 4A
Location ID: 448844



Photo 3 Tubing pressure gauge.



Photo 4 Braden Head pressure gauge.

Inspection Photos
Location Name: EWS 4A
Location ID: 448844



Photo 5 Casing pressure gauge.