

Inspection Photos

API: 071-08481

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 1. Facing south at the beginning of the access road. There is erosion occurring down the road and the side of the road is not stabilized. Stormwater directed down the road is causing erosion which is shown in the next photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 2. This erosion has occurred from stormwater directed down the road. This is also depositing sediment down the road below shown on photo 6.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 3. Stormwater is causing erosion down the road. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 4. There is deep erosion channel in the road caused from stormwater flowing down the road. Stormwater needs to be properly diverted with ditches, water bars, ect. and velocity needs to controlled with check dams sediment traps ect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 5. The white hard hat is placed in the erosion channel for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 6. Stormwater is directed to this area from the access road switch back above.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 7. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020

Inspection Photos



Photo 8. Sign has not been updated to reflect current Operator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 7/7/2020